

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE



In re Patent of:

Stefan MOLLER

Patent No.: 7,100,280 B2

Serial No.: 10/785,484

Issued:

September 5, 2006

Filed:

February 25, 2004

Title:

METHOD FOR PRODUCING A HEAT EXCHANGER

PETITION FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 C.F.R. § 1.322 OR § 1.323

Certificate

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

JUL 1 3 2007

of Correction

Sir:

Patentees hereby request that the above-identified U.S. patent be corrected in accordance with the attached Certificate of Correction.

I. <u>C.F.R. § 1.322</u>

The mistake was incurred through the fault of the Patent and Trademark

Office and is clearly disclosed in the records of the Office. Therefore, no fee is due.

· II. <u>C.F.R. § 1.323</u>

At least some of the mistakes were made by patentees. Therefore, a check in the amount of \$100.00 in payment of the fee set forth in 37 C.F.R. § 1.20(a) is enclosed herewith.

01 FC:1811 100.00 0

Enclosed herewith is a Form PTO-1050 listing errors that have been found in the above-identified patent. The errors are of a clerical or typographical nature or of minor

character and were made in good faith. The requested corrections do not constitute new matter or require reexamination.

III. Accordingly, patentees and their assignee respectfully request that the Patent and Trademark Office issue a Certificate of Correction pursuant to 37 C.F.R. § 1.322 or § 1.323, respectively.

Respectfully submitted,

Brion P. Henney, Reg. No. 32,542

Attorney for Patentees

MILLEN, WHITE, ZELANO & BRANIGAN, P.C.

Arlington Courthouse Plaza 1, Suite 1400

2200 Clarendon Boulevard

Arlington, Virginia 22201

Telephone: (703) 243-6333 Facsimile: (703) 243-6410

Attorney Docket No: Linde-618

Date July 11, 2007

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 7,100,280 B2

DATED: September 5, 2006

INVENTOR(S): Stefan MOLLER

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 5, line 40, reads "exchanger block each" should read -- exchanger block, each --;

Column 7, line 14, reads "of U-shaped" should read -- of the U-shaped --;

Column 7, line 19, reads "of U-shaped" should read -- of the U-shaped --;

Column 8, line 13, reads "bases surfaces" should read -- base surfaces --; and

Column 8, line 31, reads "connection occurs between" should read -- connection between

MAILING ADDRESS OF SENDER:

MIILLEN, WHITE, ZELANO & BRANIGAN, P.C Arlington Courthouse Plaza I 2200 Clarendon Blvd. Suite 1400 Arlington, Virginia 22201

PATENT NO. 7,100,280 B2

No. of additional copies

 \Longrightarrow

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.